

From: ["Wallingford, Jonni B." <wallingfordjb@cdmsmith.com>](mailto:Wallingford, Jonni B. <wallingfordjb@cdmsmith.com>)
To: ["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:Sheldrake, Sean <sheldrake.sean@epa.gov>)
["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen, Davis <Zhen.Davis@epa.gov>)
CC: ["Vickstrom, Kyle E." <vickstromke@cdmsmith.com>](mailto:Vickstrom, Kyle E. <vickstromke@cdmsmith.com>)
["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:Scott Coffey <coffeyse@cdmsmith.com>)
younghs@cdmsmith.com
Date: 8/28/2018 9:36:57 AM
Subject: Surface Sediment Sampling
Attachments: [IMG_20180828_091018143.jpg](#)
[IMG_20180828_091201432.jpg](#)
[IMG_20180828_092728202_HDR.jpg](#)

Good morning,

The Cayuse is currently stationed at SG-S016 (RM 2E), performing a 4th grab attempt. The alternate location is directly outside the Simplot taxlot, towards the Nav channel and within the SMA footprint.

Thus far, all grabs have consisted of very soft grayish brown silt with fine trace sand. Grab attempts 3 and 4 had "slight organic odor" and rootlets, as classified by the Pre-RD group. Composite sample S016 will comprise of attempts 2,3, and 4. The Cayuse will sample at target site S017 once sampling is completed at S016, and finish up at B479 and B478 this afternoon.

Jonni

Photo 1: siphoning water from sampler

Photo 2: S016 attempt #3

Photo 3: composite sample S016

Get Outlook for Android<<https://aka.ms/ghei36>>